



United States Steel Corporation
Clairton Works
400 State Street
Clairton, PA 15025

November 7, 2014

Ms. Gail Eddings
Allegheny County Health Department
Department of Air Quality
301 Thirty-Ninth Street
Pittsburgh, PA 15201

RECEIVED
NOV 19 2014
Division Director (681-600)


Subject: USS Reference Number: 14-0333
ACHD Reference Number: 17815
#1 Control Room
USS Clairton Works

Dear Gail Eddings,

The attached form confirms our verbal report of the subject incident and satisfies the requirements of paragraph IV.8 of the Title V operating permit #0052 as issued on March 27th 2012.

I certify that based on the information and belief formed after reasonable inquiry, the statements and information in this document are true, accurate, and complete. Any questions concerning this matter should be referred to Coleen M. Davis at 412-233-1015.

Sincerely,



Thomas E. Schumacher
Plant Manager
Clairton Works

CC: James W. Hagedorn (USEPA)

NOTICE OF OUTAGE OF EQUIPMENT
ARTICLE XXI - SECTION 2108.1

1. **USS Reference Number:** 14-0333
ACHD Reference Number: 17815
2. **Date & Time of Breakdown:** Date: 11/07/14 Time: 1045 hours
3. **Company Name:** U.S. Steel Corporation - USS Clairton Works
4. **Specific Equipment Involved or Affected:** #1 Control Room
5. **BAPC Permit Number (if applicable):**
6. **Location:** Clairton, PA
7. **Nature and cause of breakdown:** The C-155 Axi Compressor tripped off-line during the axi loading process. The C-150 Axi was placed into service.
8. **Identification of Emissions:**
 - A. **Type(s) (CO, NOX, SO₂, Particulates, Hydrocarbons, etc.)**
No environmental impact is expected.
 - B. **Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality).** No environmental impact is expected.
 - C. **Amount of each type emitted (or likely to be emitted).**
N/A
9. **Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so).**
A spare axi compressor was brought on line.
10. **Facility back in operation -** Date: 11/07/14 Time: 1140 hours

Reviewed by Coleen M. Davis Date 11-7-14
Coleen M. Davis
Senior Environmental Control Engineer Phone: 412-233-1015